Application No.: 10/690,634

Amendment dated: December 5, 2005

Reply to Office Action dated: June 3, 2005

REMARKS/ARGUMENTS

Claims 22-46 are pending. Claims 1-21 have been canceled and were allowed in the parent case. Claims 39 and 41 have been amended.

Claims 22, 23, 25-40 and 42-46 were rejected under the judicially created doctrine of obviousness-type double patenting. Submitted with this Amendment is a properly executed Terminal Disclaimer. Accordingly, reconsideration and withdrawal of the rejection of these claims under the doctrine of obviousness-type double patenting is respectfully requested.

The drawings were objected to for a number of informalities. First, the Office Action states that there is no description as to element "325" in Fig. 3. Applicants respectfully draw the Examiner's attention to page 24, line 2, where that element is called out in the Detailed Description section of the application. The drawings were also objected to in that Figs. 3 and 4 each include two features. As requested by the Examiner, Figs. 3 and 4 have been denoted as Figs. 3a and b and Figs. 4a and b. The Brief Description of the Drawings section has been amended as well.

Claims 24-26 and 41 were rejected under 35 U.S.C. § 112, second paragraph as failing to distinctly claim the invention. In particular claims 24 and 41 were objected to as not being clear how the memory unit can replay load instructions. Claim 24 states that the replay system is to determine one or more instructions that have not executed properly and to set a flag if a store instruction has not executed properly. Claim 24 also recites a memory execution unit that is coupled to the replay system; the memory execution unit is to execute load and store instruction. Application No.: 10/690,634

Amendment dated: December 5, 2005

Reply to Office Action dated: June 3, 2005

The claim also includes the following phrase, "wherein if the invalid store flag is set for a store

instruction, the replay system is to replay a load instruction that is later in sequence than the

invalid store instruction." The Office Action states that is not clear how the memory unit can

replay instructions since it is the replay system that replays instructions. Looking at the quoted

text of claim 24, the claim is clear that the replay system is to replay a load instruction. The

language of claim 24 does not state (in such words) that the memory execution unit is to replay

load instructions. As to claim 41, this claim has been amended to address the 112 rejection. In

view of the above, reconsideration and withdrawal of the rejection of claims 24-26 and 41 under

35 U.S.C. § 112, second paragraph is respectfully requested.

The application is believed to be in condition for allowance. Favorable action is earnestly

solicited.

The Office is hereby authorized to charge any fees required under 37 C.F.R.

§§ 1.16 or 1.17 or credit any overpayment to Kenyon and Kenyon Deposit Account

No. 11-0600.

Respectfully submitted,

Shawn W. O'Dowd

(Registration No. 34,687)

Attorneys for Intel Corporation

Date: December 5, 2005

KENYON & KENYON

1500 K Street, N.W., Suite 700

Washington, D.C. 20005

Tel.:

(202) 220-4255

Fax.: (202) 220-4201

592439_1.DOC

- 14 -

Application No.: 10/690,634

Amendment dated: December 5, 2005

Reply to Office Action dated: June 3, 2005

AMENDMENTS TO THE DRAWINGS

Proposed drawing corrections are attached to the Amendment to comply with the

Examiner's request.

The six (6) pages of formal replacement drawings which accompany the present

amendment are to replace the originally submitted informal drawings which accompanied the


subject patent application at the time of filing.

Attachment: Annotated Sheets Showing Changes

Replacement Sheets

592439_1.DOC

- 12 -



Application No.: 10/690,634 Amendment dated: December,5, 2005 Reply to Office Action dated: June 3, 2005 ANNOTATED SHEET SHOWING CHANGES

216


Load Buffer 141

Store Buffer 143

Memory Ordering Buffer (MOB) 127

Figure 2

Application No.: 10/690,634
Amendment dated: December 5, 2005
ANNOTATED SHEET SHOWING CHANGES



Load	Buffer
3)	2)) ~ 322
	320 NFO. 320
	Address 325

C 141

Figure 3b

Operation Source Destination

1) Store R4, [R1]

2) Load [X], R2

Reg.	Correct Value	incorrect Value
R	×	Y

Figure 4a

Lo	Cache System 120
Addres	Data
X	F000

Figure 46

Application No.: 10/690,634

Amendment dated: December 5, 2005

Reply to Office Action dated: June 3, 2005

ANNOTATED SHEET SHOWING CHANGES

Application No.: 10/690,634
Amendment dated: December 5, 2005
Reply to Office Action dated: June 3, 2005

5/6 Store Bufter




Figure 5

Application No.: 10/690,634
Amendment dated: December 5, 2005
Reply to Office Action dated: June 3, 2005
ANNOTATED SHEET SHOWING CHANGES




Figure 6

(Note: Figure 7 is now on same Page as Figure 6)

Application No.: 10/690,634
Amendment dated: December 5, 2005
Reply to Office Action dated: June 3, 2005
ANNOTATED SHEET SHOWING CHANGES

6/6




Figure 7

(Note: This figure is on the same page as Figure 6)

13.7